



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

MARY ANN WRIGHT
Acting Division Director

Supervisor 1021

Inspection Report
Minerals Regulatory Program
Report Date: March 1, 2005

Mine Name: Vermillion Mine
Operator or Permittee Name:
Color Country Rock
Permittee Mailing Address:
115 South Main
Veyo, Utah 84782

Permit number: S/053/076
Inspection Date: February 1, 2005

Inspector(s): Doug Jensen

Other Participants: None

Permit Status: Proposed
Current Acreages:
Total Permitted (Bonded): <5 Acres
Total Disturbed: <5 Acres

Weather: Cool, Windy
Inspection Start Time: 2:45 PM
Inspection End Time: 3:15 PM
Site location/Area Inspected (i.e. Pit #):
Access Road
Surface Ownership: BLM
Mineral Ownership: BLM
Mineral Mined: Sandstone
Type of Mine: To be a Quarry

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: February 1, 2005; Report Date: March 1, 2005
Page 2 of 2
S/053/076

Purpose of Inspection:

Found this site while inspecting other sites in the area.

Inspection Summary:

An access road (approximately ¼ mile in length) has been built into the site of the proposed quarry. The road was the only disturbance that had been made at the time of my inspection.

The Division, at the time of my inspection tour of the site, had not received a permit application for this area. Later I visited with Rody Cox (St. George BLM) and found that the plan had been approved their office and a bond had been received. I requested a copy of the plan be forwarded to the Division for our review and approval. Rody furnished a copy of this plan on my February 23 visit to the BLM office. Review of this plan, by the Division, is presently on hold awaiting the payment of the permit fees; the operator has been notified of this problem.


Directions to the site:

Access to the site is located several hundred yards beyond the access road into the Windy #3 site. Color Country Rock also operates the Windy #3 quarry.

GPS data:

None gathered.

Inspector's Signature



Date: March 1, 2005

DJ:jb

cc: Color Country Rock
Rody Cox, BLM, St. George FO

O:\M053-Washington\S0530076-Vermillion\inspections\ins-02012005.doc